





## CONECTORES REDUCIDOS HEMBRA MACHO

HEMBRA	MACHO	A	B	C	PRESION PSI DE TRABAJO
1/4	1/8	1 1/4	3/4	0.187	7500
3/8	1/8	1 3/8	7/8	0.187	5500
3/8	1/4	1 1/2	7/8	0.281	5500
1/2	1/4	1 3/4	1 1/8	0.281	5000
1/2	3/8	1 3/4	1 1/4	0.281	5000
3/4	1/4	1 7/8	1 1/4	0.281	4000
3/4	3/8	1 7/8	1 1/4	0.375	4000
3/4	1/2	2	1 1/4	0.437	4000



## ADAPTADOR HEMBRA MACHO MISMA MEDIDA

DIAM.	A	B	C	PRESION PSI TRABAJO.
1/4	1 3/8	3/4	0.281	7500
3/8	1 5/8	7/8	0.312	6000
1/2	1 7/8	1 1/8	0.437	5000
3/4	2	1 1/4	0.625	4000

